

Montageanleitung Gewichtsadapter de 50mm Single-U

1. Klappstecker vom Zapfen entfernen



2. Sondenfuss auf Zapfen setzen und Klappstecker fixieren



Assembly instructions weight connector de 50mm single-U

1. Remove the linch pin form the pin



2. Place the probe foot on the pin and fix the linch pin



Instructions de montage de 50mm single U

1. Enlever la goupille du pivot



2. Placer le pied de la sonde sur pivot et fixer la goupille



Istruzioni di montaggio adattore per zavorre de 50mm singola U

1. Rimuovere la copiglia pieghevole dal perno



2. Posizionare il piede della sonda sul perno e fissare la copiglia pieghevole

